Pt. 63, Subpt. UUUUU, Table 4

Table 4 to Subpart UUUUU of Part 63—Operating Limits for EGUs

As stated in §63.9991, you must comply with the applicable operating limits:

If you demonstrate compliance using	You must meet these operating limits
PM CPMS for an existing EGU.	Maintain the 30-boiler operating day rolling average PM CPMS output at or below the highest 1-hour average measured during the most recent performance test demonstrating compliance with the filterable PM, total non-mercury HAP metals (total HAP metals, for liquid oil-fired units), or individual non-mercury HAP metals (individual HAP metals including Hg, for liquid oil-fired units) emissions limitation(s).
2. PM CPMS for a new EGU	Maintain the 30-boiler operating day rolling average PM CPMS output determined in accordance with the requirements of §63.10023(b)(2) and obtained during the most recent performance test run demonstrating compliance with the filterable PM, total non-mercury HAP metals (total HAP metals, for liquid oil-fired units), or individual non-mercury HAP metals (individual HAP metals including Hg, for liquid oil-fired units) emissions limitation(s).

[78 FR 24090, Apr. 24, 2013]

Table 5 to Subpart UUUUU of Part 63—Performance Testing Requirements

As stated in 63.10007, you must comply with the following requirements for performance testing for existing, new or reconstructed affected sources:

Using ties, as a		You must perform the following activities, as applicable to your input- or output-based emission limit	Using ²	
Filterable Particulate matter (PM).	Emissions Testing	Select sampling ports location and the number of traverse points.	Method 1 at Appendix A–1 to part 60 of this chapter.	
		b. Determine velocity and volumetric flow-rate of the stack gas.	Method 2, 2A, 2C, 2F, 2G or 2H at Appendix A-1 or A-2 to part 60 of this chapter.	
		c. Determine oxygen and carbon dioxide concentrations of the stack gas.	Method 3A or 3B at Appendix A-2 to part 60 of this chapter, or ANSI/ ASME PTC 19.10-1981.3	
		d. Measure the moisture content of the stack gas.	Method 4 at Appendix A-3 to part 60 of this chapter.	
		e. Measure the filterable PM concentra-	Method 5 at Appendix A-3 to part 60 of this chapter.	
			For positive pressure fabric filters, Method 5D at Appendix A-3 to part 60 of this chapter for filterable PM emissions.	
			Note that the Method 5 front half temperature shall be 160° ±14 °C (320° ±25 °F).	
		f. Convert emissions concentration to lb/ MMBtu or lb/MWh emissions rates.	Method 19 F-factor methodology at Appendix A-7 to part 60 of this chapter, or calculate using mass emissions rate and electrical output data (see § 63.10007(e)).	
	OR	OR	0 11 (1),	
	PM CEMS	Install, certify, operate, and maintain the PM CEMS.	Performance Specification 11 at Appendix B to part 60 of this chapter and Procedure 2 at Appendix F to Part 60 of this chapter.	
		b. Install, certify, operate, and maintain the diluent gas, flow rate, and/or moisture monitoring systems.	Part 75 of this chapter and §§ 63.10010(a), (b), (c), and (d).	
		c. Convert hourly emissions concentra- tions to 30 boiler operating day rolling average lb/MMBtu or lb/MWh emis- sions rates.	Method 19 F-factor methodology at Appendix A-7 to part 60 of this chapter, or calculate using mass emissions rate and electrical output data (see § 63.10007(e)).	
2. Total or individual non-Hg HAP metals.	Emissions Testing	Select sampling ports location and the number of traverse points.	Method 1 at Appendix A-1 to part 60 of this chapter.	

Environmental Protection Agency

To conduct a per- formance test for the following pollutant	Using	You must perform the following activities, as applicable to your input- or output-based emission limit	Using ²	
		b. Determine velocity and volumetric flow-rate of the stack gas.	Method 2, 2A, 2C, 2F, 2G or 2H at Appendix A-1 or A-2 to part 60 of this chapter.	
		c. Determine oxygen and carbon dioxide concentrations of the stack gas.	Method 3A or 3B at Appendix A-2 to part 60 of this chapter, or ANSI/ ASME PTC 19.10-1981.3	
		d. Measure the moisture content of the stack gas. . Measure the HAP metals emissions concentrations and determine each individual HAP metals emissions concentration, as well as the total filterable HAP metals emissions concentration and total HAP metals emissions concentration. f. Convert emissions concentrations (individual HAP metals, total filterable HAP metals, and total HAP metals) to lb/MMBtu or lb/MWh emissions rates.	Method 4 at Appendix A–3 to part 60 of this chapter. Method 29 at Appendix A–8 to part 60 of this chapter. For liquid oil-fired units, Hg is included in HAP metals and you may use Method 29, Method 30B at Appendix A–8 to part 60 of this chapter; for Method 29, you must report the front half and back half results separately. Method 19 F-factor methodology at Appendix A–7 to part 60 of this chapter, or calculate using mass emissions rate and electrical output data (see § 63.10007(e)).	
3. Hydrogen chloride (HCI) and hydrogen fluoride (HF).	Emissions Testing	a. Select sampling ports location and the number of traverse points.	Method 1 at Appendix A-1 to part 60 of this chapter.	
gen nuonue (m.).		b. Determine velocity and volumetric flow-rate of the stack gas.	Method 2, 2A, 2C, 2F, 2G or 2H at Appendix A-1 or A-2 to part 60 of this chapter.	
		c. Determine oxygen and carbon dioxide concentrations of the stack gas.	Method 3A or 3B at Appendix A-2 to part 60 of this chapter, or ANSI/ ASME PTC 19.10-1981.3	
		d. Measure the moisture content of the stack gas. e. Measure the HCl and HF emissions concentrations.	Method 4 at Appendix A–3 to part 60 of this chapter. Method 26 or Method 26A at Appendix A–8 to part 60 of this chapter or Method 320 at Appendix A to part 63 of this chapter or ASTM 6348–03³ with (1) additional quality assurance measures in footnote⁴ and (2) spiking levels nominally no greater than two times the level corresponding to the applicable emission limit. Method 26A must be used if there are entrained water droplets in the exhaust stream.	
	OB	Convert emissions concentration to lb/ MMBtu or lb/MWh emissions rates. OR	Method 19 F-factor methodology at Appendix A–7 to part 60 of this chapter, or calculate using mass emissions rate and electrical output data (see § 63.10007(e)).	
	HCl and/or HF CEMS.	a. Install, certify, operate, and maintain the HCl or HF CEMS. b. Install, certify, operate, and maintain	Appendix B of this subpart. Part 75 of this chapter and	
		the diluent gas, flow rate, and/or moisture monitoring systems. c. Convert hourly emissions concentrations to 30 boiler operating day rolling average lb/MMBtu or lb/MWh emissions rates.	§§ 63.10010(a), (b), (c), and (d). Method 19 F-factor methodology at Appendix A-7 to part 60 of this chapter, or calculate using mass emissions rate and electrical output data (see § 63.10007(e)).	
4. Mercury (Hg)	Emissions Testing	Select sampling ports location and the number of traverse points.	Method 1 at Appendix A-1 to part 60 of this chapter or Method 30B at Appen- dix A-8 for Method 30B point selec- tion.	
		b. Determine velocity and volumetric flow-rate of the stack gas.	Method 2, 2A, 2C, 2F, 2G or 2H at Appendix A-1 or A-2 to part 60 of this chapter.	
		c. Determine oxygen and carbon dioxide concentrations of the stack gas.	Method 3A or 3B at Appendix A-1 to part 60 of this chapter, or ANSI/ ASME PTC 19.10-1981.3	

Pt. 63, Subpt. UUUUU, Table 5

To conduct a per- formance test for the following pollutant	Using	You must perform the following activities, as applicable to your input- or output-based emission limit	Using ²	
		d. Measure the moisture content of the stack gas. e. Measure the Hg emission concentration.	Method 4 at Appendix A-3 to part 60 of this chapter. Method 30B at Appendix A-8 to part 60 of this chapter, ASTM D67843, or Method 29 at Appendix A-8 to part	
		f. Convert emissions concentration to lb/ TBtu or lb/GWh emission rates.	60 of this chapter, for Method 29, you must report the front half and back half results separately. Method 19 F-factor methodology at Appendix A-7 to part 60 of this chapter, or calculate using mass emissions rate and electrical output data (see § 63.10007(e)).	
	OR	OR	9 03. 10007 (e)).	
		Hg CEMS	Sections 3.2.1 and 5.1 of Appendix A of this subpart.	
		b. Install, certify, operate, and maintain the diluent gas, flow rate, and/or moisture monitoring systems.	Part 75 of this chapter and §§ 63.10010(a), (b), (c), and (d).	
		 c. Convert hourly emissions concentra- tions to 30 boiler operating day rolling average lb/TBtu or lb/GWh emissions rates. 	Section 6 of Appendix A to this subpart.	
	OR	OR		
	Sorbent trap monitoring system.	a. Install, certify, operate, and maintain the sorbent trap monitoring system.b. Install, operate, and maintain the dil-	Sections 3.2.2 and 5.2 of Appendix A to this subpart. Part 75 of this chapter and	
		uent gas, flow rate, and/or moisture monitoring systems.	§§ 63.10010(a), (b), (c), and (d).	
	OR	c. Convert emissions concentrations to 30 boiler operating day rolling average lb/TBtu or lb/GWh emissions rates. OR	Section 6 of Appendix A to this subpart.	
	LEE testing	Select sampling ports location and the number of traverse points.	Single point located at the 10% centroidal area of the duct at a port location per Method 1 at Appendix A–1 to part 60 of this chapter or Method 30B at Appendix A–8 for Method 30B point selection.	
		b. Determine velocity and volumetric flow-rate of the stack gas.	Method 2, 2A, 2C, 2F, 2G, or 2H at Appendix A-1 or A-2 to part 60 of this chapter or flow monitoring system certified per Appendix A of this subpart.	
		c. Determine oxygen and carbon dioxide concentrations of the stack gas.	Method 3A or 3B at Appendix A-1 to part 60 of this chapter, or ANSI/ ASME PTC 19.10-1981,3 or diluent gas monitoring systems certified according to Part 75 of this chapter.	
		d. Measure the moisture content of the stack gas.	Method 4 at Appendix A–3 to part 60 of this chapter, or moisture monitoring systems certified according to part 75 of this chapter.	
		e. Measure the Hg emission concentration.	Method 30B at Appendix A–8 to part 60 of this chapter; perform a 30 operating day test, with a maximum of 10 operating days per run (i.e., per pair of sorbent traps) or sorbent trap monitoring system or Hg CEMS certified per Appendix A of this subpart.	
		f. Convert emissions concentrations from the LEE test to lb/TBtu or lb/GWh emissions rates.	Method 19 F-factor methodology at Appendix A-7 to part 60 of this chapter, or calculate using mass emissions rate and electrical output data (see § 63.10007(e)).	

Pt. 63, Subpt. UUUUU, Table 6

Environmental Protection Agency

To conduct a per- formance test for the following pollutant	Using	You must perform the following activities, as applicable to your input- or output-based emission limit	out- Using ² GWh Potential maximum annual heat input are TBtu or potential maximum electrici	
		g. Convert average lb/TBtu or lb/GWh Hg emission rate to lb/year, if you are attempting to meet the 22.0 lb/year threshold.		
the CEM b. Install, c uent gas monitorir c. Convert tions to 3 average		a. Install, certify, operate, and maintain the CEMS. b. Install, operate, and maintain the diluent gas, flow rate, and/or moisture monitoring systems. c. Convert hourly emissions concentrations to 30 boiler operating day rolling average lb/MMBtu or lb/MWh emis-	Method 19 F-factor methodology at Appendix A–7 to part 60 of this chapter, or calculate using mass emissions	
		sions rates.	rate and electrical output data (see § 63.10007(e)).	

¹Regarding emissions data collected during periods of startup or shutdown, see §§ 63.10020(b) and (c) and § 63.10021(h).

Reported Result = $\frac{\text{(Measured Concentration in Stack)}}{\%R} \times 100$

 $[77 \; \mathrm{FR} \; 9464, \; \mathrm{Feb.} \; 16, \; 2012, \; \mathrm{as} \; \mathrm{amended} \; \mathrm{at} \; 78 \; \mathrm{FR} \; 24091, \; \mathrm{Apr.} \; 24, \; 2013]$

TABLE 6 TO SUBPART UUUUU OF PART 63—ESTABLISHING PM CPMS OPERATING LIMITS

As stated in §63.10007, you must comply with the following requirements for establishing operating limits:

If you have an applicable emission limit for	And you choose to establish PM CPMS operating limits, you must	And	Using	According to the following procedures
Filterable Particulate matter (PM), total non-mercury HAP metals, individual non-mercury HAP metals, total HAP metals, or individual HAP metals for an existing EGU.	Install, certify, maintain, and operate a PM CPMS for monitoring emissions discharged to the atmosphere according to § 63.10010(h)(1).	Establish a site-specific operating limit in units of PM CPMS output signal (e.g., milliamps, mg/acm, or other raw signal).	Data from the PM CPMS and the PM or HAP metals per- formance tests.	Collect PM CPMS output data during the entire period of the performance tests. Record the average hourly PM CPMS output for each test run in the three run performance test. Determine the highest 1-hour average PM CPMS measured during the performance test demonstrating compliance with the filterable PM or HAP metals emissions limitations.

¹ Regarding emissions data collected during periods of startup or shutdown, see §§ 63.10020(b) and (c) and §63.10021(h).
² See Tables 1 and 2 to this subpart for required sample volumes and/or sampling run times.
³ Incorporated by reference, see §63.14.
⁴ When using ASTM D6348–03, the following conditions must be met: (1) The test plan preparation and implementation in the Annexes to ASTM D6348–03, Sections A1 through A8 are mandatory; (2) For ASTM D6348–03 Annex A5 (Analyte Spiking Technique), the percent (%)R must be determined for each target analyte (see Equation A5.5); (3) For the ASTM D6348–03 test data to be acceptable for a target analyte, %R must be 70% ≤R ≤130%; and (4) The %R value for each compound must be reported in the test report and all field measurements corrected with the calculated %R value for that compound using the following equation: